




# **Butadiene Extraction Plant Antwerp BDex Technology Process Design**






# **BDex Extraction Antwerp Project format "EPCm"**



EPCm-Contract with Engineering, Procurement en Construction management



#### **Procurement by BASF:**

- Proprietary Equipment
- Construction Contracts



# Safety – Key Performance Indicators

- 1. Occupational safety
  - KPI = LTI (Lost Time Injury)
  - Goal: No LTI's for the total project
  - LTI according to OSHA definition
- 2. Process safety
  - KPI = FER (Fire, Explosion & Release)
  - Goal: No FER's during start up phase
  - FER according to BASF guidelines see next slide



# **Reporting Criteria KPI-FER**

### **Fires**



## **Explosions**



Releases



- Incident in a Process resulting in a Fire, Explosion/Implosion/Bursting or Release of Substance with either:
  - A Fatality or LTI Injury,
  - Property Damage ≥ 25k €
  - Release of Substances exceeding Thresholds:
    - > 100 kg for Materials with Danger Symbol
    - > 5 kg for GHS H300/H310/H330 (Former T+)
    - > 2000 kg of all other Substances
  - Off-Site Impact (Evacuation, Injury or ERPG2 detected outside Fence Line,...)



## Occupational Safety – Challenges

#### **Challenges for Occupational Safety:**

- BASF Antwerp Site regulations vs CBI corporate requirements
  - Different company cultures
  - Working at height (6ft vs 2m)
  - Use of cage ladders for access, with harness and 100% tie off
- Follow up of a strict "Balance of Consequences" policy.
- How to implement "phased" mechanical completion without compromising occupational safety guidelines.



# **Occupational Safety - Facts**

- Heavy Lifting
  - Columns for each lift a detailed Task Risk Analysis was prepared and approved lifting procedures provided
  - Butadiene sphere lifting over piperack








RWC: 0

# **Occupational Safety - Results**

#### Week 20 - 2014



- BASF


39

8

0



## **BASF Project Organization**





## **Process Safety - Definitions**

#### Generic definitions relevant for each project


- Construction zone
- Precommissioning
- Commissioning
- Start Up

#### Special definitions relevant for Butadiene project

- Passivation
- TOS : Turnover System




### **Process Safety - Timeline**





### **Construction zone – different areas**





# Pressure Test systems -> Start of Precom





# **Gradual transition from Construction to Precommissioning**

- In a certain phase of the construction (ca 60/70% completion) it is decided to switch over from area to system completion.
  - Definition of Turn Over System (TOS)
  - Precom / Com philosophy is known & procedures are available
  - Indication of the priorities in an early stage towards contractors
- Chosen for a « phased » mechanical completion concept.
  - Turnaround Management System is used as overall tool to guide the different procedures in a safe way
  - Requires switch over from Contractor to BASF tool



# TOS System – reflection on P&ID






# Detailed construction info per TOS-system






# Impact phased mechanical completion on timeline





# Build up of a Plant Organization during Construction






# **Communication & Cooperation**

- Integrated team formed with members of « Contractor » and « Owner ».
- Weekly meetings discussing:
  - Precom procedures prepared by Contractor
  - Review of procedures by Owner, inclusive input operating personnel.
  - Execution of procedures under supervision of Contractor, with support of operations personnel,
- Resulting in a win/win situation:
  - Effective support for contractor.
  - Training opportunity for operations personnel
  - Continue precom procedures during night and week-end shift



# Use of 3D model for Precom procedures





### Final result on P&ID for Precom procedure





# Similar excercise for Passivation Procedures (Owner's responsibility)

Steekschijf bij opstart. Tussen Extractieve destillatie & Si-olie (S00001 & S00003)






# Impression of passivation activities






## **Training**





# **Transition from Project to Plant Organization**





### Safety – Results

- 1. Occupational safety
  - KPI = LTI (Lost Time Injury)
  - Final result:
    - Only one minor LTI following BASF rules
    - No LTI for CB&I under OSHA
- Process safety
  - KPI = FER (Fire, Explosion & Release)
  - Final result: No FER's



# An integrated Team – Success Factor for a Safe Start Up





### **Final Conclusion + Questions**







With thanks to Ellen for the nice lay out and format!